

HOONAH AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: The Hoonah Airport is located on the eastern side of the town of Hoonah in the northern part of Southeast Alaska. Hoonah is on the northeast side of Chichagof Island accessible by air and water only. Logging and fishing are the main occupations in the area.
- District: Southeast
- Airport Manager: Gus Skafflestad
- District Maintenance Manager: Gary Hayden
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction:
 - 1992
- Pavement layout:

The Runway 5-23 pavement is 3000' x 75'. Two Taxiways, A and B, are 35' in width and provide access to each end of the Parking Apron on the north side of the runway.
- Design Aircraft: Twin Otter
- 2001 Enplanements: 9,510
- Airport Class: Non-Primary
- Last pavement condition survey: May 12, 2003
- Next planned pavement condition survey: 2006
- 2003 reported pavement maintenance and/or changed conditions:
 - No reports

Recommendations:

- Crack seal and patch as needed